

C20x Software Release Notes



C20x Software Pack AG	
Release Date:	21. December 2018
Engineer:	Markus Auer (Bucher Municipal AG)
File update:	7022069_ AG __C20x_SwPack.zip
File production:	C20x_ProductionPack_ AG .zip

Hardware & Software Summary		
Device	Previous Version (AF)	New Version (AG)
Software PLC:	2.50	2.60
Software HMI:	2.30	2.30
JetSym	5.4.1.4256	5.4.1.4256
JetViewSoft	5.3.0.4030	5.3.0.4030
JVM BL	1.11.0.00	1.11.0.00
JVM 407 OS	1.23.1.00	1.23.1.00
JVM 407B OS	4.01.0.63	4.01.0.63
Tx5 OS	C201: 0.07.3.23 C202: 0.07.3.30	C201: 0.07.3.23 C202: 0.07.3.30
IO Node OS	3.32.0.01	3.32.0.01
PRN OS	1.04.0.00	1.04.0.00

BUCHER
municipal

Confidential. All Rights Reserved
Distribution or Copies Prohibited
© 2019 Copyright Johnston Sweepers Limited

C20x Software Release Notes

Warning

**** Following JVM update, do not start engine until an “Ignition ready” key on – key off cycle is completed.****

Note

The Euro 5 machines are not supported anymore with revision AD or higher.

JVM PLC

Update: Version: 2.60

Bug Fixes:

JVM log, gateway telematics data show the engine hours

1. “Total Engine Hours” always 0.
2. “Engine Hours in Workmode Today” always 0.

JVM HMI

No changes

Tx5 PLC

No changes

BUCHER
municipal

Confidential. All Rights Reserved
Distribution or Copies Prohibited
© 2019 Copyright Johnston Sweepers Limited